Weathertzanon Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/20002BR-0152/1
Work Order Type: Weatherization

Audit Name: 20002BR-0152-Audit

CLIENT INFORMATION

Client Name: 20002BR-0152 Address:

Client ID: 20002BR-0152

Alt. Client ID: Bradley County

CLIENT CONTACT INFORMATION

20002BR-0152 Applicant/Person of Record

AGENCY INFORMATION

Agency: Bradley-Cleveland Community Services Agency Agency Phone: (423) 479-4111

Address: 155 Sixth Street SE **Fax:** (423) 479-4113

Cleveland, TN 37320 *Email Address:* jswestfield@hotmail.com

Company Name & License Number:	
Contractor's Signature:	

COMMENT

MHEA Mobile Home Est build date 1982

Client Name: 20002BR-0152
Client ID: 20002BR-0152
Alt. Client ID: Bradley County

Work Order (Bid Form)

Work Order Name: WO/20002BR-0152/1 Report Run On: 5/20/2010 DOE Weatherization Assistant

Version 8.5.0 Page 1 of 4

Measures

Me	easure 1 DW	/H Tank Insulation			Componen	ts		I	nspected	
Cor	<i>mment</i> Tank lo	ocated under kitchen cour	nter							
				Estimated			Actual			
# M	laterial / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 In	nsulation	DWH Tank Insulation	Each	1						
2 L	abor	DWH Tank Insulation	Each	1						
Oth	ner Detail									
				Measur	e Sub Total:			Sub Total:		
Fi	ield Notes:									
Me	easure 2 DW	H Pipe Insulation			Component	ts		I	nspected	
Cor	mment Est 10'									
					Estimated			Actual		
# M	laterial / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 In	nsulation	DWH Pipe Insulation	Each							
		Diviti ipe insulation	Lacii	1						
		costs to add 10' wrap to hot/cold	Lacii	1						
2 L	abor	costs to add 10' wrap to hot/cold	Each	1						
		costs to add 10' wrap to								
	abor ner Detail	costs to add 10' wrap to hot/cold								
		costs to add 10' wrap to hot/cold								
		costs to add 10' wrap to hot/cold								
		costs to add 10' wrap to hot/cold	Each	1	e Sub Total:			Sub Total:		
Oth	er Detail	costs to add 10' wrap to hot/cold	Each	1	e Sub Total:			Sub Total:		
Oth		costs to add 10' wrap to hot/cold	Each	1	e Sub Total:			Sub Total:		
Oth	er Detail	costs to add 10' wrap to hot/cold	Each	1	e Sub Total:			Sub Total:		

Report Run On: 5/20/2010

Measure 3 Install Bath	hroom Exhaust Fai	n		Componen	ts Bathro	om #1		Inspected
Comment Vent Unit to the	e Exterior							
			Estimated			Actual		
# Material / Labor Descr	iption / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Bathrolltems	oom exhaust fan	Each	1					
2 Labor Labor		Hour	1					
Other Detail								
			Measure	e Sub Total:			Sub Total:	
	rier Needed t/Crawlspace)			Componen	<i>t</i> s Crawls	space		Inspected
(Basement	t/Crawlspace)			Componen Estimated		space	Actual	Inspected
(Basement Comment Use 6 mil plast	t/Crawlspace)	Units	Qty			space		Inspected
(Basement Comment Use 6 mil plast # Material / Labor Descri 1 Health and Safety Baser	t/Crawlspace) tic.	<i>Units</i> SqFt		Estimated	<u> </u>		Actual	
(Basement Comment Use 6 mil plast # Material / Labor Descr. 1 Health and Safety Baser vapor	t/Crawlspace) tic. tiption / Comment ment / crawlspace barrier		Qty	Estimated	<u> </u>		Actual	
(Basement Comment Use 6 mil plast # Material / Labor Descri 1 Health and Safety Items Vapor	t/Crawlspace) tic. tiption / Comment ment / crawlspace barrier	SqFt	Qty 1	Estimated	<u> </u>		Actual	
(Basement Comment Use 6 mil plast # Material / Labor Descri 1 Health and Safety Baser vapor 2 Labor Labor	t/Crawlspace) tic. tiption / Comment ment / crawlspace barrier	SqFt	Qty 1	Estimated	<u> </u>		Actual	
(Basement Comment Use 6 mil plast # Material / Labor Descri 1 Health and Safety Baser vapor 2 Labor Labor	t/Crawlspace) tic. tiption / Comment ment / crawlspace barrier	SqFt	Qty 1	Estimated	<u> </u>		Actual	
(Basement Comment Use 6 mil plast # Material / Labor Description 1 Health and Safety Baser vapor 2 Labor Labor	t/Crawlspace) tic. tiption / Comment ment / crawlspace barrier	SqFt Hour	Qty 1 1	Estimated	<u> </u>	Qty	Actual	

DOE Weatherization Assistant Version 8.5.0 Page 3 of 4

Report Run On: 5/20/2010

Measure 5 White Roof Coating (SF)			Components Use Grey Paint					Inspected
Comment Gray o	n request for bad rust.							
			Estimated					
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Construction Materials/Hardwa e	ır	SqFt	980					
Other Detail								
			Measur	e Sub Total:] .	Sub Total:	
Field Notes:								
						0.14"		
	ndow sealing			Componen	its Doors	& Win	dows	Inspected
	ws (W-1,2, 3) Doors (DR		ad to c	ool				
name a	and door need to be wea	illei suippe	eu lo si	eai Estimated	,		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows	Window Sealing	Each Window	5					
	caulking interior / exterio	or						
2 Labor	Window Sealing	Each Window						
3 Other	Window Sealing	Each Window						
Other Detail								
			Measur	e Sub Total:] ,	Sub Total:	
Field Notes:				L				
Ticia Notes.								
		Work Or	der Gra	nd Total:		Gran	d Total:	

Client Name: 20002BR-0152
Client ID: 20002BR-0152
Alt. Client ID: Bradley County

Work Order (Bid Form)

Work Order Name: WO/20002BR-0152/1 Report Run On: 5/20/2010 DOE Weatherization Assistant

Version 8.5.0 Page 4 of 4